

Notes:

1. This drawing is to be read in conjunction with all Architect's drawings and Specification and all relevant contract documentation.
2. Drawings must not be scaled. The contractor is to verify all dimensions and details on site, and is to report any discrepancies to the architect immediately.
3. The contractor is to carry out everything necessary for the proper execution of the works whether or not shown on the drawings or described in the Specification provided the same may reasonably be inferred therefrom.
4. All work is to comply with relevant British Standards and Codes of Practice in respect of materials and workmanship, and site procedure and organisation, and specifically with BS 8000-0:2014.
5. If in doubt - ask!

Items 11.1 - 11.10 specialist joiner to carefully dismantle choir stalls, investigate reasons for its collapse, carry out repairs subject to Architect's inspection and instruction, and reinstate choir stalls on completion



CHOIR STALLS



CHOIR STALLS - DETAIL SHOWING COLLAPSE AND SPOILED STONework



Item 12.4 rake and render defective spandrel panel

SOUTH AISLE ROOF - SPANDREL WALL PANEL



Item 12.10 replace defective ashlar stone in new stone

CHANCEL - SE CORNER

drawing title PHOTOS IDENTIFYING PROPOSED WORKS		ASHLEY COURTNEY RIBA AABC ARCHITECT 36 Roseford Road, Cambridge CB4 2HD tel: 01223 750610 email: ac@ashleycourtney.co.uk				
client COTON PCC	job title URGENT REPAIRS	scale NTS	date NOV 2020	job no. 20-27	dwg no. 09	rev